

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: 1FDWF36578EB43826

Vehicle manufacturer/model: Ford/F-Series Super Duty

Year of manufacture: 2008

Vehicle Software Version: V50.65

Repair State: 1

Inspection Result

There are 3 issues for Power system:

- 1.Intake Camshaft Position Timing - Over Retarded, Bank 1
- 2.Crankshaft-Camshaft Positions Correlation, Bank 1
- 3.On-Board Diagnostic (OBD) Systems Readiness Test Incomplete

There are 3 issues for Safety and Security system:

- 1.Front Driver's Safety Belt Buckle Switch Circuit Error
- 2.Battery Voltage Low
- 3.FR Wheel Speed Sensor Input Signal Lost

Professional Report

Restraint Control Module(RCM)

Abnormal 2 ^

DTC Qty (2)

B2691-E0

Front Driver's Safety Belt Buckle Switch Circuit Error

Continuous Memory DTCs

B1318-A0

Battery Voltage Low

Continuous Memory DTCs

Powertrain Control Module (PCM)

Abnormal 3 ^

DTC Qty (3)

P0012-FF

Intake Camshaft Position Timing - Over Retarded, Bank 1

Continuous Memory DTCs

P0016-FF

Crankshaft-Camshaft Positions Correlation, Bank 1

Continuous Memory DTCs

P1000-FF

On-Board Diagnostic (OBD) Systems Readiness Test Incomplete

Continuous Memory DTCs

Anti-lock Braking System(ABS)

Abnormal 1 ^

DTC Qty (1)

C1234-30

FR Wheel Speed Sensor Input Signal Lost

Continuous Memory DTCs

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.