

# Inspection Report

This report is created by

**LAUNCH**

---

## Vehicle Information

VIN: 4KXXXXXXXX88J802130  
Vehicle manufacturer/model: EOBD/  
Year of manufacture:  
Vehicle Software Version: V23.12  
Repair State: 1

---

## Inspection Result

---

There are 2 issues for Vehicle body system:  
1.O2 Sensor Circuit High Voltage Bank 2 Sensor 1  
2.System Too Lean Bank 2

## Professional Report

---

EOBD

Abnormal 2 ^

---

### DTC Qty (2)

P0152	O2 Sensor Circuit High Voltage Bank 2 Sensor 1	Pending
P0174	System Too Lean Bank 2	Pending

---

## Disclaimer

---

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.