

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: WD3PE8CB6C5710775

Vehicle manufacturer/model: MERCEDES-BENZ/

Year of manufacture:

Odometer: 349405

Vehicle Software Version: V21.95

Repair State: 1

Inspection Result

There are 7 issues for Power system:

- 1.The Regeneration Frequency Of The Diesel Particulate Filter Is Not OK.
- 2.Regeneration Of Diesel Particulate Filter Not Completed Successfully.
- 3.Diesel Particulate Filter - The Soot Content Of The Particulate Filter Is Too High For Regeneration.
- 4.Diesel Particulate Filter - The Soot Content Of The Particulate Filter Is Too High For Regeneration.
- 5.Component B90/3 (Right EKAS End Position Measurement Sensor) Is Defective. / Component B90/2 (Left EKAS End Position Measurement Sensor) Is Defective.
- 6.Component Y77/8 (Boost Pressure Regulator) Reports A Fault.
- 7.B28/20 (Diesel Particulate Filter Differential Pressure Sensor) - Signal Implausible

There are 1 issues for Safety and Security system:

- 1.N30/4 (Electronic Stability Program (ESP)) : Undervoltage
-

Inspections are normal for Power system

- 1.EWM - Electronic Selector Lever Module
- 2.TCM - Transmission Control Module

Inspections are normal for Safety and Security system

- 1.SRS(Supplemental Restraint System)

Professional Report

CDI4 6 Cylinder

Abnormal 7 ^

DTC Qty (7)

111500	The Regeneration Frequency Of The Diesel Particulate Filter Is Not OK.	Stored
111600	Regeneration Of Diesel Particulate Filter Not Completed Successfully.	Stored
11A700	Diesel Particulate Filter - The Soot Content Of The Particulate Filter Is Too High For Regeneration.	Current And Stored
13AF00	Diesel Particulate Filter - The Soot Content Of The Particulate Filter Is Too High For Regeneration.	Current And Stored
10CB00	Component B90/3 (Right EKAS End Position Measurement Sensor) Is Defective. / Component B90/2 (Left EKAS End Position Measurement Sensor) Is Defective.	Stored
126800	Component Y77/8 (Boost Pressure Regulator) Reports A Fault.	Stored
15FE00	B28/20 (Diesel Particulate Filter Differential Pressure Sensor) - Signal Implausible	Stored

EWM - Electronic Selector Lever Module

Normal v

ESP9 - Electronic Stability Program

Abnormal 1 ^

DTC Qty (1)

C011000	N30/4 (Electronic Stability Program (ESP)) : Undervoltage	Stored
---------	---	--------

TCM - Transmission Control Module

Normal v

SRS(Supplemental Restraint System)

Normal v

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.