

# Inspection Report

This report is created by

**LAUNCH**

---

## Vehicle Information

**VIN:** 1FDXF46P85ED06412

**Vehicle manufacturer/model:** FORD/F-450 F-Series

**Year of manufacture:** 2005

**Vehicle Software Version:** V50.65

**Repair State:** 1

---

## Inspection Result

---

**There are 4 issues for Power system:**

- 1.TFT Circuit Range/Performance Error
  - 2.TFT (Transmission Fluid Temperature) Sensor Circuit High Voltage Input
  - 3.Transmission Control System Failure
  - 4.Water In Fuel Condition
- 

**Inspections are normal for Safety and Security system**

- 1.Restraint Control Module(RCM)

## Professional Report

---

**Transmission Control Module(TCM)**

Abnormal 2 ^

---

### DTC Qty (2)

P0710-FF

TFT Circuit Range/Performance Error

Continuous Memory DTCs

P0713-FF

TFT (Transmission Fluid Temperature) Sensor Circuit High Voltage Input

Continuous Memory DTCs

Restraint Control Module(RCM)

Normal

Powertrain Control Module (PCM)

Abnormal 2

**DTC Qty (2)**

P0700-60

Transmission Control System Failure

Continuous Memory DTCs

P2269-60

Water In Fuel Condition

Continuous Memory DTCs

**Disclaimer**

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.