

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: JHMGE8G39CS000004

Vehicle manufacturer/model: Honda/FIT

Year of manufacture: 2012

Odometer: 435492

Vehicle Software Version: V49.70

Repair State: 1

Inspection Result

There are 1 issues for Power system:

1.EVAP CVS Circuit Voltage Low

There are 2 issues for Safety and Security system:

1.Right-Front Wheel Speed Sensor Circuit Malfunction

2.Modulator-Control Unit Power Source Circuit (IG) Low Voltage

Inspections are normal for Safety and Security system

1.Supplemental Inflatable Restraint System (SRS)

2.Seat Weight Sensor (SWS)

Professional Report

Supplemental Inflatable Restraint System (SRS)

Normal 

Anti-lock Braking System (ABS)

Abnormal 2 

DTC Qty (2)

11-11	Right-Front Wheel Speed Sensor Circuit Malfunction	Current ABS
--------------	---	-------------

61-11	Modulator-Control Unit Power Source Circuit (IG) Low Voltage	Current ABS
--------------	---	-------------

Seat Weight Sensor (SWS)	Normal ▼
---------------------------------	---

Engine Control Module (ECM)	Abnormal 1 ^
------------------------------------	---

DTC Qty (1)

P0498	EVAP CVS Circuit Voltage Low	Temporary PGM-FI
--------------	-------------------------------------	------------------

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.