

# Inspection Report

This report is created by

**LAUNCH**

---

## Vehicle Information

**VIN:** 1FMHK8F80BGA37709

**Vehicle manufacturer/model:** Ford/Explorer Limited

**Year of manufacture:** 2011

**Odometer:** 347648

**Vehicle Software Version:** V50.65

**Repair State:** 1

---

## Inspection Result

**There are 3 issues for Power system:**

- 1.Crankshaft Position - Camshaft Position Correlation - Bank #1 Sensor B
- 2.Misfire Detected In Cylinder #3
- 3.Engine Misfire Detected on Startup (First 1000 Revolutions)

**There are 2 issues for Safety and Security system:**

- 1.Occupant Classification System
- 2.Battery Voltage

---

## Professional Report

**Restraint Control Module(RCM)**

Abnormal 1 ^

---

### DTC Qty (1)

**B00A0:63-08**

**Occupant Classification System**

Continuous Memory DTCs

**Powertrain Control Module (PCM)**

Abnormal 3 ^

**DTC Qty (3)**

P0017:00-27	Crankshaft Position - Camshaft Position Correlation - Bank #1 Sensor B	Continuous Memory DTCs
P0303:00-27	Misfire Detected In Cylinder #3	Continuous Memory DTCs
P0316:00-2F	Engine Misfire Detected on Startup (First 1000 Revolutions)	Continuous Memory DTCs

**Anti-lock Braking System(ABS)**

Abnormal 1 ^

**DTC Qty (1)**

U3003:17-68	Battery Voltage	Continuous Memory DTCs
-------------	-----------------	------------------------

**Disclaimer**

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.