

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: 1FTPX18L53NA50947

Vehicle manufacturer/model: FORD/F-150

Year of manufacture: 2003

Odometer: 27422

Vehicle Software Version: V50.65

Repair State: 1

Inspection Result

There are 1 issues for Power system:

- 1.On-Board Diagnostic (OBD) Systems Readiness Test Incomplete

There are 4 issues for Safety and Security system:

- 1.Battery Voltage Low
- 2.Lamp Airbag Warning Indicator Circuit Fault
- 3.Battery Voltage Out Of Range
- 4.Brake Warning Light Output Shorted To Ground

Professional Report

Restraint Control Module(RCM)

Abnormal 2 ^

DTC Qty (2)

B1318 **Battery Voltage Low**

Continuous Memory DTCs

B1869

Lamp Airbag Warning Indicator Circuit Fault

Continuous Memory DTCs

Powertrain Control Module (PCM)

Abnormal 1 ^

DTC Qty (1)

P1000

On-Board Diagnostic (OBD) Systems Readiness Test Incomplete

Continuous Memory DTCs

Anti-Lock Braking System/Traction Control Module(ABS/TCS)

Abnormal 2 ^

DTC Qty (2)

B1676

Battery Voltage Out Of Range

Continuous Memory DTCs

C1226

Brake Warning Light Output Shorted To Ground

Continuous Memory DTCs

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.