

Item	SN	Condition
Violin 3/4 E.R. Pfretzschner	Made 1989	Large crack; scratched; wood inside instrument
Violin 4/4 Robelli	114706	Large crack on face
Violin 4/4 Shepley	95	Large crack; scratched
Violin 4/4 Mendini	20004527	Crack on face; missing parts
Violin 4/4 Mueller	B7627	Crack on face; soundpost down
Violin 4/4 Strobel	MA090051	Cracks on face; soundpost down
Violin 4/4 Mendini	2201700372	Crack on face
Violin 4/4 Cremona	5V-175	Back seams coming undone
Violin 1/2 Ji Strings	None	Back seams coming undone
Violin 4/4 Mueller Etude	7850	Crack on face; missing parts
Violin 3/4 Cremona	110191	Large crack on face
Viola Becker	2000	Peg box cracked
Cello 3/4 Kroger	8918	Endpin screw broken; small crack
Cello 3/4 Mueller	T692	Back seams coming undone
Cello 3/4 Mueller Etude	J8425	Large crack on face
Cello 3/4 Mueller Etude	J6206	Crack at endpin
Cello 1/2 Mueller Etude	J7959	Crack on face
Viola 14 Cremona	VLA1713	Large crack on face
Violin 3/4 Suzuki	NS-20 202643	Cracks on face
Violin 1/2 Cremona	44323	Huge crack
Violin 3/4 None listed	81897D	Crack at face hole
Bass San Lorenz		Cracked deemed unfixable