

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: 3VWST71K76M627239

Vehicle manufacturer/model: VW/Jetta 2.5 TDI

Year of manufacture: 2006

Odometer: 504200

Vehicle Software Version: V29.10

Repair State: 1

Inspection Result

There are 5 issues for Power system:

- 1.Glow Plug Cylinder 3:Open Circuit
- 2.Glow Plug Cylinder 4:Open Circuit
- 3.Glow Plug Cylinder 2:Open Circuit
- 4.Engine Coolant Temperature Sensor 2 Circuit Low
- 5.Activation Of Pump/Injector Valves:Electrical Error In Circuit

There are 4 issues for Safety and Security system:

- 1.Supply Voltage
- 2.Vehicle Voltage Terminal 30
- 3.Please refer to manual
- 4.Right Rear ABS Wheel Speed Sensor

Professional Report

15 Airbag

Abnormal 1 ^

DTC Qty (1)

00532

Supply Voltage

Lower Limit Exceeded

03 Brake Electronics

Abnormal 3 ^

DTC Qty (3)

00668

Vehicle Voltage Terminal 30

Upper Limit Exceeded

24,00,e0,a7(U20a7)

Please refer to manual

Cannot Be Tested At This Time

00287

Right Rear ABS Wheel Speed Sensor

Mechanical Failure

01 Engine Electronics

Abnormal 5 ^

DTC Qty (5)

P161C

Glow Plug Cylinder 3:Open Circuit

P161D

Glow Plug Cylinder 4:Open Circuit

P161B

Glow Plug Cylinder 2:Open Circuit

P2184

Engine Coolant Temperature Sensor 2 Circuit Low

P1664

Activation Of Pump/Injector Valves:Electrical Error In Circuit

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.