

## Inspection Report

This report is created by

LAUNCH

### Vehicle Information

VIN : 1D4PU4GK3AW175118

Vehicle manufacturer/model: Chrysler/Nitro

Year of manufacture: 2010

Vehicle Software Version : V35.50

Repair State : 1

### Inspection Result

There are 4 issues for Vehicle body system :

- 1.Implausible Left Wheel Distance Signal Received
- 2.LR Solenoid Circuit
- 3.O2 Sensor 1/2 Circuit High
- 4.Battery/System Voltage Low

### Professional Report

#### Powertrain Control Module (PCM)

Abnormal **4**

#### DTC Qty (4)

U1417	Implausible Left Wheel Distance Signal Received	Active
P0750	LR Solenoid Circuit	Stored
P0138	O2 Sensor 1/2 Circuit High	Pending
P0562	Battery/System Voltage Low	Pending

### Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live

diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.